



BSI No.: [G16D304](#)  
 Publish Date: [05/17/2016](#)  
 Subject: [\[Update: May 16, 2016\] e-STUDIO5005AC/5008A Series : Release of AirPrint Support Patch](#)

Model: e-STUDIO2008A, e-STUDIO2508A, e-STUDIO3008A, e-STUDIO3508A, e-STUDIO4508A, e-STUDIO5008A, e-STUDIO2505AC, e-STUDIO3005AC, e-STUDIO3505AC, e-STUDIO4505AC, e-STUDIO5005AC

Category	Field Application	UNIT
C14 Addition of the Function	F01 For your information	U23 Firmware in machine, U91 Engine (Copier) firmware

FactoryApplication:

Parts Availability in Tokyo:

## CONTENT

Update: May 16, 2016

The patch corresponding to the following models and F/W versions were released.  
 (A patch is common for eachmodel.)

e-STUDIO5005AC Series: System F/W "T373HD0W1015" and "T373HD0W1016"

e-STUDIO5008A Series: System F/W "T410HD0W1015" and "T410HD0W1016"

We would like to inform you of the release of the AirPrint support patch.

### **1. Release Content**

The patch supporting the AirPrint function will be released.

You can perform printing immediately from iPad, iPhone, iPod touch or Mac without installing a driver or downloading software.

For details, refer to the following attached files.

[AirPrint\\_OM\\_EN \(EBN\)\\_Ver00-F2.pdf](#)

### **2. Release Version**

Model	System F/W	Update method	File name	Capacity	Date and time
e-STUDIO5005AC Series	T373HD0W1015 /T373HD0W1016	From TopAccess	<a href="#">T373PA0W1017X.zip</a>	<a href="#">224,608 bytes</a>	<a href="#">2016/05/07 11:17</a>
		From USB media	<a href="#">T373HDPW1017X.zip</a>	<a href="#">224,701 bytes</a>	<a href="#">2016/05/07 11:17</a>
e-STUDIO5008A Series	T410HD0W1015 /T410HD0W1016	From TopAccess	<a href="#">T410PA0W1017X.zip</a>	<a href="#">234,221 bytes</a>	<a href="#">2016/05/07 11:37</a>
		From USB media	<a href="#">T410HDPW1017X.zip</a>	<a href="#">234,280 bytes</a>	<a href="#">2016/05/07 11:37</a>

The system firmware versions after the patch file is installed individually are as follows.

Model	08 Code	System F/W version
e-STUDIO5005AC Series	08-8952	<a href="#">T373HD0W1017X</a>
e-STUDIO5008A Series	08-8952	<a href="#">T410HD0W1017X</a>

\*When you install patch, MFP reboot a few times automatically to reflect settings. Please wait for MFP to boot normally.

### **3. Installation procedure**

For install procedure, please refer "11.2.4 Update procedure" in service manual.

4. Patch File

Model	Update method	File name
e-STUDIO5005AC Series	From TopAccess	<a href="#">T373PA0W1017X.zip</a>
	From USB media	<a href="#">T373HDPW1017X.zip</a>
e-STUDIO5008A Series	From TopAccess	<a href="#">T410PA0W1017X.zip</a>
	From USB media	<a href="#">T410HDPW1017X.zip</a>